OUT56716

CSD

IPD PD

PSD-ICB TID

PID

PAG DIAXX

SPAD NSA-LO

DIA-AP

P 172022Z

FM NPIC WASHDC

TO RUCSC/SAC OFFUTT AFB OMAHA NEB
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAA/2D RTS BARKSDALE AFB LA
RUEKDA/DIA WASHDC
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUWGAA/2AF BARKSDALE AFB LA
BT
S E C R E T CITE NPIC 5474.

1935 CEP 17 20 34Z

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

- 1. CAMERA B 23 WAS USED IN MISSION 8043 FLOWN ON 15 SEPTEMBER 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.
 - 2. ORIGINAL NEGATIVE:
 - A. EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.
- B. 9R SIDE: A WAVERING PLUS DENSITY STREAK IS PRESENT
 INTERMITTENTLY WITHIN THE MISSION. EXAMPLES ARE LOCATED IN FRAMES 2 0 SEP 1965
 244 AND 347. THERE IS A HEAT SPLICE BETWEEN FRAMES 967/968.

 ANOTHER HEAT SPLICE IS LOCATED IN FRAME 1144 ACCOMPANIED BY PROCESSING STREAKS AND IRREGULAR PLUS DENSITY STREAKS. A MANUFACTURING ADMIN

 SPLICE IS LOCATED IN FRAME 354.
- C. 9L SIDE: WAVERING PLUS DENSITY STREAKS OCCUR INTERMITTENTLY THROUGHOUT THE MISSION NEAR THE INBOARD EDGE. EXAMPLES
 ARE ON FRAMES 18, 582/583, 708, 882, 1094 TO 1099, 1718 AND
 2113. EMULSION DIGS ARE NOTED ON FRAMES 624, 634, 641, 645, 667
 AND 672. HEAT SPLICES ARE PRESENT BETWEEN FRAMES 47/48, 109/
 110, 1184/1185, 1251/1252, 2164/2165 AND THROUGH FRAME 1160.
 - D. BOTH SIDES: EDGE FOG AND EDGE STATIC OCCURS ALONG BOTH

-2-

EDGES THROUGHOUT THE MISSION. ROLLER CHATTER IS PRESENT ALONG BOTH EDGES. THE LAST TITLED FRAME IS 2216.

- E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.
- 3. POSITIVE:
 - A. THE PI SUITABILITY IS GOOD.
 - B. THE PRINTING AND PROCESSING WAS GOOD.
 - C. CLOUDS DEGRADED OR OBSCURED 5 PERCENT OF THE MISSION.

GP-1

SECRET

-- END OF MESSAGE--